


*Debra Reynolds*  
433 High View Ranch Drive  
Cedar Creek, TX. 78612



February 12, 2013

In Re: Nissan Radiator/Transmission Cooler Litigation, Case no. 10cv07493

Debra Ann Reynolds  
433 High View Ranch Drive  
Cedar Creek, TX 78612  
512-289-0730

Objection to the Settlement


I owned the following vehicle, which I bought used. Within a month of purchasing this vehicle, I started having the problems of the transmission/radiator issue. My objection in this case is that Of the mileage of the vehicle. When I was able to have this vehicle repaired, I had 122,589 miles on the vehicle. I object to the fact that it must have only 100,000 recorded miles. This issue cost me in excess of \$4000. I have obtained receipts from the dealer which I took it to upon having the issue and the transmission shop that eventually did the replacement. As you can see by my attached documentation, I have had multiple problems with this vehicle. All leading to the transmission/radiator issue. Please consider my objection. I sunk quite a large sum of money on this vehicle before I finally gave up and sold it.

2005 –  
Nissan Frontier LX  
S/n: 1N6AD074X5C441168  
Mileage at time of repair: 122589

Thank You.

A handwritten signature in cursive script, appearing to read "Debra Reynolds".

Debra Reynolds  
433 High View Ranch Drive  
Cedar Creek, TX 78612  
512-289-0730



NNS



\*\*\*AUTO\*\*SCH 3-DIGIT 786  
Claim #: NNS-11216070001 1159215  
03-0637256-B  
Debra Reynolds  
433 High View Ranch Dr  
Cedar Creek, TX 78612-4901



Name/Address Changes (if any):

First Name

Last Name

Address

City

State

Zip

## Claim Form

In Re: Nissan Radiator/Transmission Cooler Litigation, Case No. 10-cv-07493

Please return by regular mail to:  
Nissan Radiator/Transmission Cooler Reimbursement Claims Headquarters  
P.O. Box 43132, Providence, RI 02940-3132  
All claims must be post marked by June 7, 2013.

For Official Use Only

### I. Claimant Contact Information

Daytime Telephone Number <sup>512</sup> (512 289 0730) 289-0730  
Evening Telephone Number (512 289 0730) - - - - -

Email dragonfly403@hotmail.c

### II. Claimant Verification Information

1. Did you purchase or lease a 2005 – 2010 Nissan Pathfinder, Nissan Frontier, or Nissan Xterra vehicle?

Yes




No



If so, please provide the following information:

2005 Year FRONTIER Model



Vehicle Identification Number

2. Did you pay out of your own pocket for repairs to your vehicle because of cross-contamination of engine coolant and transmission fluid caused by a defect in the radiator?

Yes



No



If you answered "NO" to question 1 OR question 2, you are not eligible to submit a claim.

If you answered "YES" to questions 1 through 2:

- (a) How much did you pay for parts, labor, and towing in connection with the repair?

\$ 4,082.11

- (b) What was your odometer mileage at the time of repair?

1	2	2	5	8	9
---	---	---	---	---	---

 miles



**TRANSMISSION  
SPECIALISTS**

**Repair Order**

**Facility Location:**  
2425 W. Ben White Blvd. Austin, TX 78704 512-707-1396

<b>Customer Information</b>		
Date: 01/18/2010	Customer Name: REYNLDS, DEBBIE	RO ID: -251785
Address: 433 HIGH VIEW RANCH CEDAR CREEK, null 78612		Phone: 512-289-0730

<b>Vehicle Information</b>					
Year: 2005	Make: Nissan	Model: Frontier	Eng Size: 4.0	Trans Type:	Mileage: 122589
VIN: 1N6AD07UX5C441168			License: TX, AFO-6203		

<p align="center"><b>Inspection</b></p> <p>Remove and Dismantle Transmission. Internal Inspection of Transmission Reassemble and Install. The transmission shop Can Operate this Vehicle for Testing and Inspection at my risk.</p> <p>Signature _____</p>	<p align="center"><b>Work Authorization</b></p> <p>I hereby authorize the repair work to be done along with necessary materials. The transmission shop Can Operate this Vehicle for Testing and Inspection at my risk.</p> <p>Signature _____</p>
--	---

Service	Comments	Price
Other	A+ 22 Point Diagnosis Free Diagnostic Service	\$ 0.00
A+ Transmission Inspection Service		\$ 585.00
A+ Transmission Reconditioned Transmission Service with a Rebuilt Exchanged Torque Converter		\$ 3,482.11
Credit Inspection Service		-\$ 585.00
Other	See Comments 24 month or 24,000 mile limited local warranty this shop only	\$ 0.00
Other	Coupon Discount	-\$ 100.00
Rent Car Credit		-\$ 100.00
Other	A PLUS TRANSMISSION INSTALLED A NEW RADIATOR	\$ 350.00
Other	A PLUS TRANSMISSION INSTALLED A NEW VALVE BODY. CUSTOMER NEGLECTED TO GO WITH AFTER MARKET	\$ 450.00
<b>Total:</b>		<b>\$ 4,082.11</b>

Date	Payment	Amount
02/01/2010	Cash null	\$ 4,082.11
<b>Total Payments:</b>		<b>\$ 4,082.11</b>
<b>Balance Due:</b>		<b>\$ 0.00</b>

<p align="center"><b>Completion Certificate</b></p> <p>I received the Car Specified Above, and a copy of this repair order.</p> <p>Signature _____</p>	<p align="center"><b>Warranty Information</b></p> <p>Warranty Papers:</p> <p>Signature _____</p>
--	--

<p><b>Notice Pursuant to Section 70.001, Texas Property Code</b></p> <p>I am the person or the agent acting on behalf of the person who is obligated to pay for the motor vehicle subject to this repair contract. I understand that this vehicle is subject to repossession in accordance with Section 9.503, Texas Business and Commerce Code, if a written order for payment for repairs of the vehicle is stopped, dishonored because of insufficient funds, no funds, or because the drawer or maker of the order has no account or the account on which it is drawn has been closed.</p> <p>Signature _____</p>
---

**COPY**

JAN 31, 2013 HISTORY - SPECIFIC VEHICLE

Store 07 SERVC01 PORT 5198 3010

CUSTOMER NAME		DEBBIE REYNOLDS		SERIAL NO. 1N6AD07UX5C441168	
R.O. NO. 218880	RO.DATE 12/29/2009	DEPT (S,B,P,Q) S SERVICE		ADVISOR NO. 4816	
[7 OF 7]	[4 OF 7]	MILEAGE 122307/122307			
OPERATION NO. 03N1Z		OP. DESC. ENGINE MECH DIAG			
SALE TYPE (C/W/I) C		TECH.NO(S). 4823			
COMPLAINT ON START UP SHE HEARS A CLUNK ON RT FT SIDE OF ENGINE AREA					
CAUSE					
CORRECTION FOUND LEFT AND RIGHT ENGINE MOUNT BROKEN REC. REPLACING TO CORRECT					
WARRANTY	CLAIM NO.	OPERATION NO.	CLAIM NO.	OPERATION NO.	
CAMPAIGN NO.	CAMPAIGN DESC.				
CAMPAIGN NO.	CAMPAIGN DESC.				

(1=COMMENTS) (2=RECOMMENDATIONS) (3=CCC SCREEN) (E=ENTER) (JOB#) (P=PRINT) (TAB)

JAN 31, 2013 HISTORY - SPECIFIC VEHICLE

Store 07 SERVC01 PORT 5198 3010

CUSTOMER NAME DEBBIE REYNOLDS

SERIAL NO. 1N6AD07UX5C441168

R.O. NO. 218880

RO. DATE 12/29/2009

DEPT (S,B,P,Q) S SERVICE

[7 OF 7]

[2 OF 7]

MILEAGE 122307/122307

ADVISOR NO. 4816

OPERATION NO. 14NIZ

OP. DESC.

FRT SUSP DIAG

SALE TYPE (C/W/I) C

TECH.NO(S).

4823

COMPLAINT CUSTOMER STATES THAT SHE HEARS A SQUEAK WHEN GOING OVER  
BUMPS FRONT PART OF TRUCKCAUSE CONFIRMED NOISE FOUND LEFT FRONT BODY MOUNT LOOSE CAUSING  
SQUEAKS OVER BUMPS TIGHTNED BODY MOUNTS TO CORRECT

CORRECTION

WARRANTY

CLAIM NO.

OPERATION NO.

CLAIM NO.

OPERATION NO.

CAMPAIGN NO.

CAMPAIGN DESC.

CAMPAIGN NO.

CAMPAIGN DESC.

(1=COMMENTS) (2=RECOMMENDATIONS) (3=CCC SCREEN) (E=ENTER) (JOB#) (P=PRINT) (TAB)

JAN 31, 2013 HISTORY - SPECIFIC VEHICLE

Store 07 SERVC01 PORT 5198 3010

CUSTOMER NAME DEBBIE REYNOLDS

SERIAL NO. 1N6AD07UX5C441168

R.O. NO. 218880

RO.DATE 12/29/2009

DEPT (S,B,P,Q) S SERVICE

[7 OF 7]

[3 OF 7]

MILEAGE 122307/122307

ADVISOR NO. 4816

OPERATION NO. 75NIZMERGE

OP. DESC.

MERGED OPERATION

SALE TYPE (C/W/I) C

TECH.NO(S).

4823

COMPLAINT ROOF RACK RATTLES ALOT

CAUSE

CORRECTION TIGHTNED ROOF RACK MOUNTING BOLTS TO CORRECT

WARRANTY

CLAIM NO.

OPERATION NO.

CLAIM NO.

OPERATION NO.

CAMPAIGN NO.

CAMPAIGN DESC.

CAMPAIGN NO.

CAMPAIGN DESC.

(1=COMMENTS) (2=RECOMMENDATIONS) (3=CCC SCREEN) (E=ENTER) (JOB#) (P=PRINT) (TAB)

JAN 31, 2013 HISTORY - SPECIFIC VEHICLE

Store 07 SERVC01 PORT 5198 3010

CUSTOMER NAME DEBBIE REYNOLDS

SERIAL NO. 1N6AD07UX5C441168

R.O. NO. 218880

RO.DATE 12/29/2009

DEPT (S,B,P,Q) S SERVICE

[7 OF 7]

[7 OF 7]

MILEAGE 122307/122307

ADVISOR NO. 4816

OPERATION NO. 18NIZMERGE

OP. DESC.

MERGED OPERATION

SALE TYPE (C/W/I) C

TECH.NO(S).

4823

COMPLAINT CUSTOMER REQUEST 4 WHEEL ALIGNMENT

CAUSE

DUE TO TIME/MILEAGE

CORRECTION 4 WHEEL ALIGNMENT COMPLETED

WARRANTY

CLAIM NO.

OPERATION NO.

CLAIM NO.

OPERATION NO.

CAMPAIGN NO.

CAMPAIGN DESC.

CAMPAIGN NO.

CAMPAIGN DESC.

(1=COMMENTS) (2=RECOMMENDATIONS) (3=CCC SCREEN) (E=ENTER) (JOB#) (P=PRINT) (TAB)

JAN 31, 2013 HISTORY - SPECIFIC VEHICLE

Store 07 SERVC01 PORT 5198 3010

CUSTOMER NAME DEBBIE REYNOLDS

SERIAL NO. 1N6AD07UX5C441168

R.O. NO. 218880

RO.DATE 12/29/2009

DEPT (S,B,P,Q) S SERVICE

[7 OF 7]

[1 OF 7]

MILEAGE 122307/122307

ADVISOR NO. 4816

OPERATION NO. 15NIZMERGE

OP. DESC.

MERGED OPERATION

SALE TYPE (C/W/I) C

TECH.NO(S).

4823

COMPLAINT CUSTOMER STATES WHEN DRIVING UP HILL ABOUT 40MPH SOMETIMES  
AT 60MPH SHE FEELS A SHIMMYCAUSE CONFIRMED COMPLAINT ON INSPECTION FOUND LEFT FRONT WHEEL  
BEARING/HUB WORN REC. REPLACING OF BEARING AND HUB TO CORREC  
CORRECTION REPLACED HUB AND BEARING

WARRANTY

CLAIM NO.

OPERATION NO.

CLAIM NO.

OPERATION NO.

CAMPAIGN NO.

CAMPAIGN DESC.

CAMPAIGN NO.

CAMPAIGN DESC.

(1=COMMENTS) (2=RECOMMENDATIONS) (3=CCC SCREEN) (E=ENTER) (JOB#) (P=PRINT) (TAB)



JAN 31, 2013 HISTORY - SPECIFIC VEHICLE

Store 07 SERVC01 PORT 5198 3010

CUSTOMER NAME DEBBIE REYNOLDS

SERIAL NO. 1N6AD07UX5C441168

R.O. NO. 219111

RO.DATE 01/04/2010

DEPT (S,B,P,Q) S SERVICE

[6 OF 7]

[1 OF 4]

MILEAGE 122539/122539

ADVISOR NO. 4816

OPERATION NO. 03NIZMERGE

OP. DESC.

MERGED OPERATION

SALE TYPE (C/W/I) C

TECH.NO(S).

4823

COMPLAINT CUSTOMER STATES CHECK ENGINE LIGHT IS ON -- CHECK AND ADVISE

CAUSE FOUND MULTIPLE CODES STORED IN TRANSMISSION ALL CODES POINT  
 TO MECHANICAL FAILURE SOLENOIDS STICKING DUE TO MILEAGE REC.  
 CORRECTION REC. REPLACING TRANSMISSION ASSEMBLY TO CORRECT

WARRANTY

CLAIM NO.

OPERATION NO.

CLAIM NO.

OPERATION NO.

CAMPAIGN NO.

CAMPAIGN DESC.

CAMPAIGN NO.

CAMPAIGN DESC.

(1=COMMENTS) (2=RECOMMENDATIONS) (3=CCC SCREEN) (E=ENTER) (JOB#) (P=PRINT) (TAB)

JAN 31, 2013 HISTORY - SPECIFIC VEHICLE

Store 07 SERVC01 PORT 5198 3010

CUSTOMER NAME DEBBIE REYNOLDS

SERIAL NO. 1N6AD07UX5C441168

R.O. NO. 224439

RO.DATE 04/17/2010

DEPT (S,B,P,Q) S SERVICE

[5 OF 7]

[1 OF 3]

MILEAGE 129319/129319

ADVISOR NO. 4816

OPERATION NO. 01NIZ01

OP. DESC.

\*3750 INTERVAL SERV

SALE TYPE (C/W/I) C

TECH.NO(S).

259

COMPLAINT CUSTOMER REQUESTS OIL AND FILTER CHANGE

CAUSE

DUE TO TIME AND MILEAGE

CORRECTION PERFORMED OIL AND FILTER CHANGE

WARRANTY

CLAIM NO.

OPERATION NO.

CLAIM NO.

OPERATION NO.

CAMPAIGN NO.

CAMPAIGN DESC.

CAMPAIGN NO.

CAMPAIGN DESC.

(1=COMMENTS) (2=RECOMMENDATIONS) (3=CCC SCREEN) (E=ENTER) (JOB#) (P=PRINT) (TAB)

JAN 31, 2013 HISTORY - SPECIFIC VEHICLE Store 07 SERVC01 PORT 5198 3010

CUSTOMER NAME		DEBBIE REYNOLDS		SERIAL NO. 1N6AD07UX5C441168	
R.O. NO. 224439	RO.DATE 04/17/2010	DEPT (S,B,P,Q) S SERVICE		ADVISOR NO. 4816	
[5 OF 7]	[2 OF 3]	MILEAGE 129319/129319			
OPERATION NO. 01NIZMERGE		OP. DESC.		MERGED OPERATION	
SALE TYPE (C/W/I) C		TECH.NO(S).		259	
COMPLAINT ROTATE AND BALANCE TIRES					
CAUSE: CUSTOMER REQUEST					
CORRECTION ROTATED AND BALANCED TIRES					
WARRANTY	CLAIM NO.	OPERATION NO.	CLAIM NO.	OPERATION NO.	
CAMPAIGN NO.	CAMPAIGN DESC.				
CAMPAIGN NO.	CAMPAIGN DESC.				

(1=COMMENTS) (2=RECOMMENDATIONS) (3=CCC SCREEN) (E=ENTER) (JOB#) (P=PRINT) (TAB)

JAN 31, 2013 HISTORY - SPECIFIC VEHICLE

Store 07 SERVC01 PORT 5198 3010

CUSTOMER NAME		DEBBIE REYNOLDS		SERIAL NO. 1N6AD07UX5C441168	
R.O. NO. 231497	RO.DATE 08/30/2010	DEPT (S,B,P,Q) S SERVICE			
[4 OF 7]	[1 OF 1]	MILEAGE 139957/139957		ADVISOR NO. 4816	
OPERATION NO. 20NIZMERGE		OP. DESC. MERGED OPERATION			
SALE TYPE (C/W/I) C		TECH.NO(S). 5262			
COMPLAINT DRIVER SIDE WINDOW NOT WORKING					
CAUSE					
CORRECTION INSTALLED DRIVER SIDE WINDOW MOTOR AND REGULATOR					
WARRANTY	CLAIM NO.	OPERATION NO.	CLAIM NO.	OPERATION NO.	
CAMPAIGN NO.	CAMPAIGN DESC.				
CAMPAIGN NO.	CAMPAIGN DESC.				

(1=COMMENTS) (2=RECOMMENDATIONS) (3=CCC SCREEN) (E=ENTER) (JOB#) (P=PRINT) (TAB)

CUSTOMER NAME    DEBBIE REYNOLDS

R.O. NO. 238412 RO. DATE 01/10/2011  
[3 OF 7] [1 OF 1] MILEAGE 147778/147778

OPERATION NO.	77NIZMERGE	OP. DESC.	MERGED OPERATION
SALE TYPE	(C/W/I) K	FROM 10/1/81	

SALE TYPE (C/W/I) W TECH.NO(S). 5289

COMPLAINT RECALL CAMPAIGN ECM RELAY #PC068

CAUSE SAFETY CAMPAIGN ECM RELAY

CORRECTION REPLACE ECM RELAY

WARRANTY	CLAIM NO.	OPERATION NO.	CLAIM NO.	OPERATION NO.
	238412-01	PC0680		

CAMPAIGN NO.	CAMPAIGN DESC.
CAMPAIGN NO.	CAMPAIGN DESC.

WFO / C-10 6107 / 10 / 70

CUSTOMER NAME    DEBBIE REYNOLDS

SERIAL NO. 1N6AD07UX5C441168

OPERATION NO.	04N12MERGE	OP. DESC.	MERGED OPERATION
SALE TYPE (C/W/I)	C	TECH.NO(S).	5289
COMPLAINT	CUSTOMER STATES 2 HOSES LOOSE @ FIREWALL ON PASSANGER SIDE. SPRAYING COOLANT.		
CAUSE	HOSES BROKE OFF CAUSING VEHICLE TO OVER HEAT.		

CORRECTION NEED TO REPLACE HEATER HOSES, THERMOSTAT, COOLANT TEMP SENSOR  
AND PERFORM COOLANT FLUSH.. CUSTOMER TURNED DOWN ALL WORK.

[illegible]

CAMPAIGN NO.	CAMPAIGN DESC.
CAMPAIGN NO.	CAMPAIGN DESC.

(1=COMMENTS) (2=RECOMMENDATIONS) (3=CCC SCREEN) (E=ENTER) (JOB#) (P=PRINT) (TAB)

JAN 31, 2013 HISTORY - SPECIFIC VEHICLE Store 07 SERVC01 PORT 5198 3010

CUSTOMER NAME DEBBIE REYNOLDS

SERIAL NO. 1N6AD07UX5C441168

R.O. NO. 250673

RO.DATE 08/16/2011

DEPT (S,B,P,Q) S SERVICE

[1 OF 7]

[1 OF 3]

MILEAGE 162726/162726

ADVISOR NO. 4672

OPERATION NO. 08NIZ

OP. DESC.

CHARGING SYS DIAG

SALE TYPE (C/W/I) C

TECH.NO(S).

5289

COMPLAINT CUSTOMER STATES THAT THE CRANK POSITION SENSOR NEEDS TO BE REPLACED.

CAUSE

P0335 CRANK SENSOR READING BAD TRACK, NOT STARTING.

CORRECTION REPLACED SENSOR TO FIX PROBLEM.

WARRANTY

CLAIM NO.

OPERATION NO.

CLAIM NO.

OPERATION NO.

CAMPAIGN NO.

CAMPAIGN DESC.

CAMPAIGN NO.

CAMPAIGN DESC.

(1=COMMENTS) (2=RECOMMENDATIONS) (3=CCC SCREEN) (E=ENTER) (JOB#) (P=PRINT) (TAB)

TO 7CHRISTINA  
FROM 7JOHNM  
SUBJECT Re:  
DATE 10:00AM CST 31 JAN 2013

1 OF 1

| CALL 1-800-258-7008 OPT 7  
| TELL THEM YOU ARE FROM 2608 AND WANT THAT VIN UNARCHIVED  
| Reply to message from 7CHRISTINA  
| Date - 09:58AM CST 31 JAN 2013  
| To: 7JOHNM  
| HELLO DEAR SIR,  
  
|  
|  
| COULD YOU PLEASE UNARCHIVE THE FOLLOWING VIN FOR ME:  
  
| 3N1BB51D11L496830  
|  
|  
| THANK YOU AND HAVE A FABULOUS DAY!

More--->

(B=BACK) (R=REPLY) (F=FORWARD) (D=DELETE) (N=NEXT) (P=PRINT) (U=UP) (L=LIST)